HOMEOWNER LIMITED WARRANTY Issue 2.16 – Dated 3/24/16

INDEX

SECTION	NUMBER	SUBJECT	PAGE
l.		INTRODUCTION	2
II.		HOMEOWNER RESPONSIBILITY	3
III.		PERFORMANCE STANDARDS	4
	1.	- SITE WORK	5
	2.	- Driveways	6
	3.	- CONCRETE	7 - 8
	4.	- MASONRY	9
	5.	- WOOD & PLASTIC	10 - 11
	6.	- THERMAL & MOISTURE	12 - 14
	7.	- Doors & Windows	15 - 18
	8.	- FINISHES	19 - 22
	9.	- Specialties	23
	10.	- CABINETS & COUNTERTOPS	24 - 25
	11.	- PLUMBING	26
	12.	- Heating & Cooling	27
	13.	- VENTILATION	28
	14.	- ELECTRICAL	29
IV.		Systems - 1st & 2nd Years	30
	15.	- PLUMBING SYSTEM	30
	16.	- VENTILATION SYSTEM	31
	17.	- ELECTRICAL SYSTEM	31
V.		Building Codes	32
VI.		Exclusions	33

I. INTRODUCTION

Please Read This Carefully. The following is intended to acquaint you with the responsibilities of Builder under this Limited Warranty. The Warranty coverage is for a period of one year from the date of settlement. Some items are however, specifically indicated to be covered for a second year. If a defect is noted during the Warranty period, the Performance Standards will be used to determine Builder's obligation under this Limited warranty. If a specific defect is not addressed in the Performance Standards, one of the following standards will be used to determine Builder's obligation under this Limited Warranty:

- Locally adopted codes; or
- Model codes covering building, mechanical, plumbing, and electrical systems; or
- Codes of nearby jurisdictions; or
- Locally accepted building practices.

Please note that coverage on certain items varies within the Limited Warranty period and some items rely on proper maintenance by the Home Owner (and/or The Homeowners Association in instances relating to common elements).

Important Notes:

- 1. Builder's responsibility is strictly limited to the repair or replacement (at Builder's sole discretion) of defective items as provided herein. Under no circumstances shall Builder be deemed to be responsible for damages to other items which may occur as a consequence of such defects.
- 2. The equipment, appliances, components and materials used in the construction of your new home are made by major, reputable manufacturing companies who administer their own warranty programs. Warranty requests regarding such items must be addressed directly to the manufacturer and will be handled in accordance with their procedures and guidelines. There is no additional warranty on such items beyond those provided by their manufacturers and Builder has no responsibility in this regard.
- 3. This warranty is not transferable.
- 4. If Builder is not given the first right to resolve a defect, warranty coverage will no longer apply to that item. No claims to seek reimbursement will be accepted.

II. HOME OWNER RESPONSIBILITY

The Home requires an active maintenance effort on the Home Owner's part to reduce the likelihood of damage due to neglect, improper maintenance, or abnormal use. Some specific Home Owner responsibilities are included under specific topics in Sections III - Performance Standards.

It is the duty of the homeowner to notify Builder immediately in writing of any defect covered under this Limited Warranty.

NOTE: Damage caused or made worse by Home Owner negligence, improper maintenance, or improper operation is expressly excluded under this Limited Warranty.

III. PERFORMANCE STANDARDS

The Performance Standards list specific items (defects) within each separate area of coverage. The standards are expressed in terms of performance criteria. For easy comprehension, the format is designed as follows:

- 1. **Possible Deficiency -** a brief statement of problems that may be encountered.
- 2. **Performance Standard -** a performance standard relating to a specific deficiency.
- 3. **Responsibility -** a statement of the corrective action required of Builder to repair the deficiency or a statement of the Home Owner's maintenance responsibilities.

Workmanship and Materials, First Year Only

Applies to problems encountered in the first year that are caused by defective materials or faulty workmanship in the following categories:

- 1. Site Work
- 2. Driveways
- 3. Concrete
- 4. Masonry
- 5. Wood and Plastic
- 6. Thermal and Moisture Protection
- 7. Doors and Windows
- 8. Finishes
- 9. Specialties
- 10. Cabinets & Countertops
- 11. Plumbing
- 12. Heating and Cooling
- 13. Ventilation
- 14. Electrical

Systems, First and Second Year

Applies to the overall functioning of the systems, not their individual components, fixtures, or equipment:

- 15. Plumbing System
- 16. Ventilation System
- 17. Electrical System

Manufacturer's Warranties

In the case of items that are covered by manufacturer's warranties the terms of such warranties shall take precedence over the present document.

1. SITE WORK

A. SITE GRADING	A. SITE GRADING	
Possible Deficiency	Settling of ground around foundation, utility trenches or other	
	areas.	
Performance Standard	Settling of ground around foundation walls, utility trenches or other	
	filled areas shall not interfere with water drainage away from the	
	Home.	
Responsibility	Builder shall fill settled areas during the first year of the Limited	
	Warranty period. Home Owner, (or the Home Owner's Association	
	in condominium) shall be responsible for removal and replacement	
	of shrubs or other landscaping affected by placement of such fill.	

Note: Planting of trees and shrubs by the Home Owner or replacement of soil around the foundation with highly absorbent soil may interfere with water drainage and would nullify Builder warranties regarding grading and drainage.

B. SITE DRAINAGE	
Possible Deficiency	Improper drainage of the site.
Performance Standard	The necessary grades and swales shall have been established by Builder to insure proper drainage away from the Home. Standing or ponding water shall not remain for extended periods (generally no more than 24 hours) in the immediate area after a rain, except that in storm water management areas, a longer period can be anticipated. The possibility of standing water after an unusually heavy rainfall should be anticipated.
Responsibility	Builder is responsible only for initially establishing the proper grades and swales. The Home Owner (or the Association in a condominium) is responsible for maintaining such grades and swales once they have been properly established. No grading determination shall be made while there is frost or snow on the ground, or while the ground is saturated.

C. SOIL EROSION	
Possible Deficiency	The site has soil erosion.
Performance Standard	Due to the uncertainty of weather conditions, Builder is not responsible for washouts or soil erosion which may occur after the settlement date of the property
Responsibility	None.

2. DRIVEWAYS

A. LOW SPOTS	
Possible Deficiency	Low spots in driveway in which water pockets appear.
Performance Standard	No measurable water depth exceeding ½" is permitted on blacktop
	driveways 24 hours after a rainfall.
Responsibility	Builder will make necessary corrections to meet Performance
	Standard by filling with blacktop. The finished repair should be
	feathered and smoothed. Color variations are to be expected.

B. CRACKING	
Possible Deficiency	Excessive cracking of blacktop driveway.
Performance Standard	Blacktop driveway should not develop cracks more than ½"wide.
Responsibility Builder will make necessary corrections on the cracks to mee	
	Performance Standard by patching. Finished repair to be
	feathered and smoothed. Color variations are to be expected.

C. CHIPPING	
Possible Deficiency	Chipping at edges of blacktop.
Performance Standard	This section of blacktop is tamped in by hand and will crack more than ½" and cave in when heavy vehicles are driven over it.
Responsibility	None.

3. CONCRETE

A. SEPARATION	
Possible Deficiency	Separation or movement of concrete slabs within the structure at
	expansion and contraction joints.
Performance Standard	Concrete slabs within the structure are designed to move at
	expansion and contraction joints.
Responsibility	None.

B. WALL CRACKS	
Possible Deficiency	Concrete basement or foundation wall cracks.
Performance Standard	Shrinkage cracks are not unusual in concrete foundation walls.
	Cracks greater than 1/4 inch in width shall be repaired.
Responsibility	Builder will fill cracks to meet Performance Standard.

C. FLOOR CRACKS		
Possible Deficiency	Cracking of Concrete floor slabs, patios, stoops, porches.	
Performance Standard		
	exceeding 1/4 inch in width or 3/16 inch in vertical displacement	
	shall be repaired.	
Responsibility	Builder will repair cracks to meet Performance Standard by filling,	
	surface patching or other methods as required. Color variations	
	are to be expected.	

D. GARAGE FLOOR CRACKS	
Possible Deficiency	Cracking of slab in garage.
Performance Standard	Minor cracks in concrete floors are to be expected. Cracks in garage slabs in excess of 1/4 inch in width or 1/4 inch in vertical displacement shall be repaired.
Responsibility	Builder will repair cracks to meet Performance Standard by filling, surface patching or other methods as required. Color variations are to be expected.

E. UNEVEN FLOORS/SLABS	
Possible Deficiency	Uneven concrete floors/slabs.
Performance Standard	Except where a floor or portion of floor has been designed for specific drainage purposes, concrete floors in rooms designed for habitability shall not have pits, depressions or areas of unevenness exceeding 1/2 inch in 32 inches.
Responsibility	Builder will correct or repair to meet the Performance Standard.

3. CONCRETE - continued

F. CRACKS IN SLAB ON GRADE FLOORS	
Possible Deficiency	Cracks in concrete slab-on-grade floors with finished flooring.
Performance Standard	Cracks which rupture the finished flooring material shall be
	repaired.
Responsibility	Builder will repair cracks, as necessary, so as not to be readily apparent when the finished flooring material is in place. ("See also Performance Standard, Finishes.")

G. PITTING, SCALING, O	OR SPALLING
Possible Deficiency	Pitting, scaling or spalling of concrete work covered by this Limited
	Warranty.
Performance Standard	Concrete surfaces shall not disintegrate to the extent that the
	aggregate is exposed and loosened under normal conditions of
	weathering and use. Minor pitting of surface is excluded.
Responsibility	Builder will repair defective concrete surfaces. Builder is not
	responsible for deterioration caused by salt, chemicals,
	mechanical implements and other factors beyond its control. Color
	variations are to be expected.

H. SEPARATING STOOPS, STEPS, GARAGE FLOORS	
Possible Deficiency	Separating of stoops, steps or garage floors.
Performance Standard	Stoops, steps or garage floors shall not separate in excess of 1/2
	inch from the house structures.
Responsibility	Builder will caulk or fill gap.

I. STANDING WATER	
Possible Deficiency	Standing water on stoops.
Performance Standard	Water should drain from outdoor stoops and steps. Possibility of minor water standing on stoops for a short period after rain can be anticipated.
Responsibility	Builder will take necessary corrective action to meet the Performance Standard.

J. WALLS OUT OF PLUMB	
Possible Deficiency	Foundation walls out of plumb.
Performance Standard	Foundation walls should not be out of plumb great than 1½ inches
	in 8 feet when measured from base to top of wall.
Responsibility	Builder will take necessary corrective action to meet the
	Performance Standard.

4. MASONRY

A. WALLS CRACKS	
Possible Deficiency	Basement or foundation wall cracks.
Performance Standard	Small cracks not affecting structural stability are not unusual in masonry foundation walls. Cracks greater than 1/4 inch in width shall be repaired.
Responsibility	Builder will repair cracks in excess of 1/4 inch by pointing or patching. Color variations are to be expected.

B. CRACKS IN EXTERIOR	
Possible Deficiency	Cracks in exterior masonry walls or flexlite finishes.
Performance Standard	Small cracks due to shrinkage are common in mortar joints in masonry construction. Small cracks are common in flexlite finishes due to the home settling and the expansion and contracting due to the outside elements. Cracks greater than 1/4 inch in width are considered excessive.
Responsibility	Builder will repair cracks to meet the Performance Standard by pointing or patching. Color variations are to be expected.

C. SEPARATION	
Possible Deficiency	The basement wall is cracked (horizontal or vertical separation).
Performance Standard	Cracks in basement walls shall not allow exterior water to leak and
	drip into the basement.
Responsibility	Builder will repair cracks to meet the-Performance Standard when
	leaks are present.

D. WATER IN BASEMENT	
Possible Deficiency	Water in basement due to rising of the water table.
Performance Standard	When the water table rises above the basement floor it may seep
	through the joint where walls and floor meet or it can overflow the
	sump pit.
Responsibility	Builder has no responsibility when water enters the basement due
	to water table rising.
	In all cases the Home Owner should consider the following:
	Store items off of ground level.
	Install a sump pump.
	Test your sump pump periodically.
	 Have back up power set in place for your sump pump.

Note: All deficiencies relating to masonry shall be reported and repairs made during the first year of the Limited Warranty period. Builder will not be responsible for color variation between old and new mortar.

5. WOOD AND PLASTIC

A. FLOOR SQUEAKS	
Possible Deficiency	Floors squeak or sub-floor appears loose.
Performance Standard	Floor squeaks and loose sub-floor are often temporary conditions common to new construction, and a squeak-proof floor cannot be guaranteed.
Responsibility	Builder will correct the problem only if caused by an underlying construction defect.

B. UNEVEN FLOORS	
Possible Deficiency	Uneven wood floors.
Performance Standard	Floors shall not have more than ¼ inch ridge or depression within
	any 32 inch measurement when measured parallel to the joists.
	Allowable floor and ceiling joist deflections are governed by the
	applicable building code. (Note: floors may have substantial
	variations when measured at right angle to the joists, due to joist
	shrinkage which is a common occurrence).
Responsibility	Builder will correct or repair to meet Performance Standard.

C. BOWED WALLS	
Possible Deficiency	Bowed walls.
Performance Standard	All interior and exterior walls have slight variances on their finished surfaces. Bowing of walls should not detract from or blemish the walls' finished surfaces. Walls should not bow more than 1/2 inch out of line within any 32 inch horizontal or 3/4 inch within any eight 8 foot vertical measurement.
Responsibility	Builder will repair to meet Performance Standard.

D. WALLS OUT OF PLUMB	
Possible Deficiency	Out-of plumb walls.
Performance Standard	Walls should not be more than 3/8 inch out of plumb for any 32
	inch vertical measurement.
Responsibility	Builder will repair to meet the Performance Standard.

E. TRIM WORKMANSHIP	
Possible Deficiency	Poor quality of interior trim workmanship.
Performance Standard	Joints in moldings or joint between moldings and adjacent surface
	shall not result in open joints exceeding 1/8 inch in width.
Responsibility	Builder will repair defective joints to meet the-Performance
	Standard. Caulking is acceptable.

5. WOOD AND PLASTIC - continued

F. SQUEAKS IN STAIRS	
Possible Deficiency	Squeaking stair riser or tread
Performance Standard	Loud squeaks caused by loose stair riser or tread, with noticeable
	movement, are unacceptable, but totally squeak-proof stair risers
	or treads cannot be guaranteed.
Responsibility	Builder will fasten any loose risers or take other corrective action
	to eliminate squeaking to the extent possible within reasonable
	repair capability without removing treads or ceiling finishes.

G. DECK BOARDS	
Possible Deficiency	Wood decking boards are split, warped or cupped.
Performance Standard	Wood decking boards do crack, warp, or cup over time.
Responsibility	Builder will only repair extreme cases where a board is completely
	split through in the first six (6) months after the settlement date.

H. WOOD BEAMS	
Possible Deficiency	Wood beams are split, warped or cupped.
Performance Standard	Wood beams do crack, warp, or cup over time.
Responsibility	Builder will only repair or replace extreme cases where a board is greater than 3 ½ inches in thickness and greater ¾ inch in split, warped, or cupped.

I. DECK NOT LEVEL	
Possible Deficiency	Wood or composite deck not level.
Performance Standard	No point on the deck surface shall be more than 1 inch higher or lower than any other deck surface point within10 feet on a line parallel to the house, or proportional multiples of the preceding dimensions.
Responsibility	Builder will repair the deck as necessary to meet the Performance Standard. A slope of approximately 1/8 inch per foot is desirable in the perpendicular direction to shed water and assist in preventing ice build-up.

6. THERMAL AND MOISTURE

A. WATERPROOFING	
Possible Deficiency	Leaks in basement.
Performance Standard	Leaks resulting in actual trickling of water shall be repaired. Leaks caused by improper landscaping or failure to maintain proper grades by Home Owner or Home Owner's Association are not covered by this Limited Warranty. Dampness of the walls or floors may occur in new construction and is not considered a deficiency. (Also see note to Section 1 A. Site Grading)
Responsibility	Builder will take such action as necessary to correct basement leaks except where the cause is determined to result from Home Owner action or negligence.

B. DAMPNESS	
Possible Deficiency	Dampness is evident on basement wall or floor.
Performance Standard	Dampness caused by wicking through the basement walls or floor and condensation of water vapor on cool walls and floors are not the responsibility of Builder
Responsibility	None. Dampness prevention is the responsibility of the Home Owner.

C. INSULATION	
Possible Deficiency	Insufficient insulation.
Performance Standard	Insulation shall be installed in accordance with the building specifications and applicable energy and building code requirements
Responsibility	Builder will install insulation in sufficient amounts to meet Performance Standard

D. LOUVERS AND VENTS	
Possible Deficiency	Leaks due to snow or rain driven into the attic through louvers or
	vents
Performance Standard	Attic vents and/or louvers must be provided for proper ventilation
	of the attic space of the structure
Responsibility	None.

E. ROOFING AND SIDING	
Possible Deficiency	Ice build-up on roof.
Performance Standard	During prolonged cold spells, ice build-up is likely to occur at the eaves of a roof. This condition occurs when snow and ice accumulate and gutters and down spouts freeze up, and it may lead to leakage.
Responsibility	Prevention of ice build-up on the roof is a Home Owner or Home Owner's Association maintenance item.

6. THERMAL AND MOISTURE - continued

F. ROOFING/SIDING LEAKS	
Possible Deficiency	Roof or flashing leaks.
Performance Standard	Roof or flashing shall not leak under normally anticipated
	conditions, except where cause is determined to result from ice
	build-up or Home Owner or Home Owner's Association action or
	negligence.
Responsibility	Builder will repair any verified roof or flashing leaks not caused by
	ice build-up or Home Owner action or negligence.

G. ROOFING/SIDING DE	G. ROOFING/SIDING DE-LAMINATION	
Possible Deficiency	De-lamination of veneer siding or joint separation.	
Performance Standard	All siding shall be installed according to the manufacturer and	
	industry accepted standards. Separations and de-lamination shall	
	be repaired or replaced	
Responsibility	Builder will repair or replace siding as needed unless caused by	
	Home Owner's or Home Owner's Association neglect. Repaired	
	area may not match in color and/or texture. For surfaces requiring	
	paint, Builder will paint only the new materials that may not match	
	original surface color.	

H. ROOF BOWS/WAVY	
Possible Deficiency	Roof sheathing is wavy or appears bowed.
Performance Standard	Roof sheathing shall not bow more than ½ inch in 2 feet.
Responsibility	Builder will straighten bowed roof sheathing or correct swollen
	joints as necessary to meet the Performance Standard.

I. ROOFING NAILS	
Possible Deficiency	Roofing nails are exposed.
Performance Standard	Nail heads should be sealed to prevent leakage.
Responsibility	Builder shall repair as necessary to meet the Performance
	Standard.

J. GUTTERS LEAK	
Possible Deficiency	Gutters and/or down spouts leak.
Performance Standard	Gutters and down spouts shall not leak due to seam separations in
	excess of ½". Gutters at seam locations may, however, drip once the caulk at the seam dries. Gutters may also overflow during heavy rain.
Responsibility	Builder will repair seam separations in excess of ½". It is a Home Owner or Home Owner's Association, responsibility to maintain gutters and to keep gutters and down spouts free of leaves and debris that could cause overflow.

6. THERMAL AND MOISTURE - continued

K. GUTTERS	
Possible Deficiency	Water standing in gutters.
Performance Standard	When the gutter is unobstructed by debris, the water level shall not exceed one (1) inch in depth. Industry practice is to install gutters approximately level. Consequently, it is possible that small amounts of water will stand in gutter.
Responsibility	Builder will correct to meet the Performance Standard.

L. ROOFING/SIDING DE	-LAMINATION
Possible Deficiency	De-lamination of veneer siding or joint separation.
Performance Standard	All siding shall be installed according to the manufacturer and
	industry accepted standards. Separations and de-lamination shall
	be repaired or replaced
Responsibility	Builder will repair or replace siding as needed unless caused by Home Owner's or Home Owner's Association neglect. Repaired area may not match in color and/or texture. For surfaces requiring paint, Builder will paint only the new materials that may not match original surface color.

M. SEALANTS	
Possible Deficiency	Leaks in exterior walls due to inadequate caulking.
Performance Standard	Joints and cracks in exterior wall surfaces and around openings
	shall be properly caulked to exclude the entry of water.
Responsibility	Builder will repair and/or caulk joints or cracks in exterior wall surfaces as required to correct deficiencies one time, during the first year of the Limited Warranty period. Even properly installed caulking will shrink and must be maintained during the life of the Home

N. EXTERIOR TRIM	
Possible Deficiency	Gaps show in exterior trim.
Performance Standard	Joints between exterior trim elements, including siding and masonry, shall not result in joints opened wider than ¼ inch. In all cases the exterior trim shall perform its function of excluding the elements.
Responsibility	Builder will repair open joints to meet Performance Standards. Caulking is acceptable.

7. DOORS AND WINDOWS

A. WOOD AND PLASTIC DOORS	
Possible Deficiency	Warpage of exterior doors.
Performance Standard	Exterior doors will warp to some degree due to temperature differential on inside and outside surfaces. However, they shall not warp to the extent that they become inoperable, cease to be weather resistant or exceed National Woodwork Manufacturers Association standards (1/4 inch, measured diagonally from corner to corner).
Responsibility	Builder will correct defective doors, during the first year of the Limited Warranty period

B. WARPING	
Possible Deficiency	Warpage of interior passage and closet doors.
Performance Standard	Interior doors (full openings) shall not warp in excess of National Woodwork Manufacturers Association Standards (1/4 inch, measured diagonally from corner to corner.)
Responsibility	Builder will correct defective doors to meet the Performance Standard during the first year of the Limited Warranty period.

C. SHRINKAGE	
Possible Deficiency	Shrinkage of insert panels show raw wood edges.
Performance Standard	Panels will shrink and expand and may expose unpainted surface.
Responsibility	None.

D. SPLITTING	
Possible Deficiency	Split in door panel.
Performance Standard	Split panels shall not allow light to be visible through the door.
Responsibility	Builder will, if light is visible, fill split and match paint or stain as
	closely as possible, one time in first year of the Limited Warranty
	period.

E. PLASTIC MOLDING	
Possible Deficiency	Plastic molding behind storm door melts from exposure to sunlight.
Performance Standard	The plastic molding behind the storm door should not melt if the storm panel is removed in warm weather and reinstalled by the Home Owner during normal maintenance operations.
Responsibility	None.

7. DOORS AND WINDOWS - continued

F. HARDWARE/EXTERIOR DOORS	
Possible Deficiency	Exterior door hardware has tarnished.
Performance Standard	Finishes on door hardware installed by Builder are covered by manufacturer's warranty.
Responsibility	None. Home Owner to contact manufacturer

G. HARDWARE/INTERIOR DOORS	
Possible Deficiency	Door hardware does not work properly.
Performance Standard	All hardware on doors should operate with ease as intended.
Responsibility	Builder will make necessary adjustments or replace door hardware
	to meet the Performance Standard.

H. SLIDER DOOR/SCREEN	
Possible Deficiency	Slider door & screen do not operate properly.
Performance Standard	Slider door & screen should slide with ease.
Responsibility	Builder will adjust doors to meet the Performance Standard one
	time if noted before the home settlement date.

I. WINDOWS	
Possible Deficiency	Air infiltrates around door or window.
Performance Standard	Some infiltration is usually noticeable around doors and windows
	especially during high winds. No daylight shall be visible around
	frame when window or door is closed.
Responsibility	Builder will correct doors to meet the Performance Standard.

J. INTERIOR DOORS	
Possible Deficiency	Interior doors do not operate properly
Performance Standard	All interior doors should operate with ease.
Responsibility	Builder will correct doors to meet the Performance Standard.

K. INTERIOR DOORS/BOTTOMS	
Possible Deficiency	Excessive openings at bottom of interior doors
Performance Standard	Passage doors from room to room that have an opening between
	the bottom of the door and the floor finish material in excess of 1
	½ inches is a deficiency. Closet doors having an opening in
	excess to 2 inches is a deficiency.
Responsibility	Builder will make necessary adjustments or replace doors to meet
	the Performance Standard

7. DOORS AND WINDOWS - continued

L. WINDOWS/AIR LEAKS	
Possible Deficiency	Air infiltrates around door or window.
Performance Standard	Some infiltration is usually noticeable around doors and windows
	especially during high winds. No daylight shall be visible around
	frame when window or door is closed.
Responsibility	Builder will correct doors to meet the Performance Standard.

M. WINDOWS/OPERATION	
Possible Deficiency	Malfunction of windows
Performance Standard	Windows shall operate with reasonable ease, as designed.
Responsibility	Builder will correct or repair to meet Performance Standards

N. WINDOWS/CONDENSTATION	
Possible Deficiency	Condensation and/or frost on windows.
Performance Standard	Windows will collect condensation on interior surfaces when extreme temperature differences and high humidity levels are present. Condensation is usually the result of climatic/humidity conditions created by the Home Owner.
Responsibility	Unless directly attributed to faulty installation, window condensation is a result of conditions beyond Builder's control. No corrective action required.

O. WINDOWS/FALL DOWN	
Possible Deficiency	Double hung windows do not stay in place when open.
	Double hung windows are permitted to move up and down within a
	2 inch tolerance when put in an open position.
Responsibility	Builder will adjust sash balances one time only.

P. GLASS/BROKEN	
Possible Deficiency	Broken glass
Performance Standard	Glass should not be damaged on the settlement date.
Responsibility	Broken glass not reported to Builder prior to closing is the Home
	Owner's responsibility.

Q. GLASS/SCRATCHED	
Possible Deficiency	Scratch on surface glass or mirror.
Performance Standard	Glass and mirrors should not have scratches visible from 10 feet
	under normal lighting conditions.
Responsibility	Builder will replace if noted before the settlement date.

7. DOORS AND WINDOWS - continued

R. GARAGE DOORS	
Possible Deficiency	Garage doors fail to operate properly, under normal use.
Performance Standard	Garage doors shall operate properly.
Responsibility	Builder will correct or adjust garage doors as required, except
	where the cause is determined to result from Home Owner action
	or negligence.

S. GARAGE DOORS/BOTTOM	
Possible Deficiency	Garage doors allow entrance of snow or water.
Performance Standard	Garage doors shall be installed as recommended by the manufacturer. Some entrance of the elements can be expected under abnormal conditions.
Responsibility	Builder will adjust or correct garage doors to meet manufacturer's recommendations.

T. WEATHER STRIPPING/SEALS	
Possible Deficiency	Air infiltration around doors and windows.
Performance Standard	Some infiltration is normally noticeable around doors and windows, especially during high winds. Poorly fitted weather-stripping shall be adjusted or replaced. It may be necessary for the Home Owner to have storm doors and windows installed to
Responsibility	provide satisfactory solutions in high wind areas. Builder will adjust or correct poorly fitted doors, windows and
,	poorly fitted weather-stripping.

U. SCREENS	
Possible Deficiency	Bent screen frames, tears or holes in screens
Performance Standard	Screens should not be damaged on the settlement date.
Responsibility	Screen damage not reported to Builder prior to the settlement date
	is the Home Owner's responsibility.

8. FINISHES

A. DRYWALL	040315
Possible Deficiency	Defects in air conditioned spaces which appear during first year of
	the Limited Warranty such as nail pops, blisters in tape or other
	blemishes.
Performance Standard	Slight "imperfections" such as nail pops, seam lines and cracks
	not exceeding 1/8 inch in width are common in gypsum wallboard
	installations and are considered acceptable.
Responsibility	Builder will repair only cracks exceeding 1/8 inch in width, one
	time only, during the first year of the limited Warranty period.
	Painting of repaired areas will be the responsibility of the Home
	Owner. (See also Performance Standard, "Painting.")

B. CERAMIC TILE	
Possible Deficiency	Ceramic tile cracks or becomes loose.
Performance Standard	Ceramic tile shall not crack or become loose.
Responsibility	Builder will replace cracked tiles and re-secure loose tiles unless the defects were caused by the Home Owner action or negligence. Builder will not be responsible for discontinued patterns or color
	variations in ceramic tile.

C. CERAMIC TILE/GROUT	
Possible Deficiency	Cracks appear in grouting of ceramic tile joints or at junctions with
	other materials such as a bathtub.
Performance Standard	Cracks in grouting of ceramic tile joints are commonly due to
	normal shrinkage conditions.
Responsibility	Builder will repair grouting if necessary one time only, during the
	first year of the Limited Warranty period. Builder will not be
	responsible for color variations or discontinued colored grout. Re-
	grouting of these cracks is a maintenance responsibility of the
	Home Owner for the life of the Home.

D. WOOD FLOORS/CRACKS	
Possible Deficiency	Cracks developing between floor boards.
Performance Standard	Cracks in excess of 1/8 inch in width shall be corrected.
Responsibility	Builder will repair cracks in excess of 1/8 inch within the first year
	of the Limited Warranty period, by filling or replacing, at Builder's
	sole discretion.

8. FINISHES - continued

E. WOOD FLOORS/NOT LEVEL	
Possible Deficiency	Wood floor is not level.
Performance Standard	Wood floors should not be ½ inch lower or higher than any other
	point within 20 feet
Responsibility	Builder will take corrective action to meet Performance Standards so that the affected area is not readily visible. Builder will not be responsible for discontinued patterns or color variations in floor covering. Levelness is both an aesthetic & functional consideration. In cases where cabinetry and countertops are affected see Section 10. CABINETS & COUNTERTOPS.

F. VINYL FLOORS/NAIL POPS 010915	
Possible Deficiency	Nail pops (fastener intrusions) appear on the face of vinyl flooring.
Performance Standard	Readily apparent nail pops which have broken the surface shall be
	repaired.
Responsibility	Builder will repair or replace with similar material, at Builder's sole
	discretion, the affected area only. Builder will not be responsible
	for discontinued patterns or color variations in the floor covering.

G. VINYL FLOORS/DEPRESSIONS 010915	
Possible Deficiency	Depressions or ridges appear in the vinyl flooring due to sub-floor irregularities.
Performance Standard	Depressions or ridges that appear in the vinyl flooring due to sub-
	floor irregularities should not exceed 1/8" in height.
Responsibility	Builder will take corrective action to meet Performance Standards
	in the affected area only. Builder will not be responsible for
	discontinued patterns or color variations in floor covering.

H. VINYL FLOORS/LOO	SENING 010915
Possible Deficiency	Vinyl flooring loses adhesion.
Performance Standard	Vinyl flooring shall not lift or bubble in excess of 1/8", or become
	unglued.
Responsibility	Builder will repair or replace, at Builder's sole discretion, only the
	affected areas. Builder will not be responsible for discontinued
	patterns or color variation of floor covering, or for problems caused
	by Home Owner neglect or abuse.

8. FINISHES - continued

I. VINYL FLOORS/GAPS	010915
Possible Deficiency	Seams or shrinkage gaps show at vinyl flooring joints.
Performance Standard	Gaps shall not exceed 1/16 inch in width in vinyl floor covering
	joints. Where dissimilar materials abut, gaps up to 1/8 inch are
	permissible.
Responsibility	Builder will repair or replace, at Builder's sole discretion, only the
	affected areas. Builder will not be responsible for discontinued
	patterns or color variation of floor covering, or for problems caused
	by Home Owner neglect or abuse.

J. VINYL FLOORS/ UND	ERLAYMENT JOINTS SHOWING THROUGH 010915
Possible Deficiency	Underlayment joints are visible through vinyl floor
Performance Standard	Underlayment joints will show through most vinyl floors, especially
	lower gauge and shiny types. However, underlayment separation
	exceeding 1/8" horizontally or vertically is not permissible.
Responsibility	Builder will repair or replace, at Builder's sole discretion, only the
	affected areas. Builder will not be responsible for discontinued
	patterns or color variation of floor covering.

K. PAINTING/EXTERIOR	
Possible Deficiency	Exterior paint or stain peels or fades.
Performance Standard	Exterior paint or stain should not peel during the first year of the
	Limited Warranty period. However, fading is normal and the
	degree is dependent on climatic conditions.
Responsibility	If paint or stain is defective, Builder will properly prepare and refinish affected areas, matching the color as close as possible. Where finish deterioration affects the majority of the wall area, the whole area will be refinished.

L. PAINTING/CONSEQUENTIAL	
Possible Deficiency	Painting required as corollary repair because of other work.
Performance Standard	Repairs required under this Limited Warranty shall be finished to
	match surrounding areas as closely as practicable, except for
	drywall repairs under section 8.A where touch up painting is the
	responsibility of the Home Owner.
Responsibility	Builder will finish repair areas as indicated. It can be expected that
	new paint may not match existing paint perfectly.

M. PAINTING - MILDEW/FUNGUS	
Possible Deficiency	Mildew or fungus on painted surfaces.
Performance Standard	Mildew or fungus will form on a painted surface due to exposure to
	weather and humidity.
Responsibility	Mildew or fungus formation is a condition Builder cannot control
	and is a Home Owner maintenance item unless it is a result of
	noncompliance with other sections of the Performance Standard.

8. FINISHES - continued

N. FLOOR FINISH	
Possible Deficiency	Deterioration of varnish or lacquer finishes.
Performance Standard	Natural finishes on interior woodwork shall not deteriorate during
	the first year of the Limited Warranty period. However, varnish
	type finishes used on the exterior will deteriorate rapidly and are
	not covered by the Limited Warranty.
Responsibility	Builder will retouch affected areas of natural finish interior
	woodwork, matching the color as closely as possible.

O. WALL COVERINGS/PEELING	
Possible Deficiency	Peeling of wall covering
Performance Standard	Peeling of wall covering shall not occur
Responsibility	Builder will repair or replace defective wall covering applications.

P. WALL COVERINGS/MIS-MATCH	
Possible Deficiency	Edge mismatching in pattern of wall covering.
Performance Standard	None.
Responsibility	None.

Q. CARPET/SEAMS	
Possible Deficiency	Open carpet seams
Performance Standard	Carpet seams will show, particularly when using "Trackless"
	carpet. The visibility of the seam varies with light conditions and
	location of the seam. However, a gap at the seam is unacceptable.
Responsibility	Builder will correct to meet Performance Standard.

R. CARPET/LOOSE	
Possible Deficiency	Carpeting becomes loose, seams separate or stretching occurs.
Performance Standard	Wall to wall carpeting, installed as the primary floor covering, when
	stretched and secured properly shall not come up, become loose,
	or separate from its point of attachment.
Responsibility	Builder will re-stretch or re-secure carpeting as needed, if original
	installation was performed by Builder.

S. CARPET/SPOTS	
Possible Deficiency	Spots on carpet, minor fading.
Performance Standard	Exposure to light may cause spots on carpet and/or minor fading.
Responsibility	None.

T. EXTERIOR FINISH	
Possible Deficiency	Cracks in exterior stucco wall surfaces.
Performance Standard	Cracks are not unusual in exterior stucco wall surfaces. Cracks greater than 1/8 inch in width shall be repaired
	greater than 1/8 inch in width shall be repaired
Responsibility	Builder will repair cracks exceeding 1/8 inch in width, one time
	only, during the first year of the Limited Warranty period.

9. SPECIALITIES

A. LOUVERS & VENTS	
Possible Deficiency	Inadequate ventilation of attics and crawl spaces.
Performance Standard	Attic and crawl spaces shall be ventilated as required by the
	appropriate building code
Responsibility	Builder shall provide for adequate ventilation. Builder will not be
	responsible for alterations to the original system

B. FIREPLACE	
Possible Deficiency	Fireplace or chimney does not draw properly.
Performance Standard	A properly designed and constructed fireplace and chimney shall function properly. It is normal that high winds can cause negative draft situations. Obstructions such as large branches of trees too close to the chimney may also cause negative draft. Some homes may be so airtight as to need to have a window opened slightly to create an effective draft.
Responsibility	Builder will correct problem caused by design or construction of the fireplace. In the case of manufactured fireplaces the manufacturer's warranty will apply.

C. FIREPLACE/CHIMNEY	
Possible Deficiency	Chimney separation from structure to which it is attached.
Performance Standard	Newly built fireplaces will often incur slight amounts of separation.
	Separation shall not exceed 1/2 inch from the main.
Responsibility	Builder will correct if standard is not met. Caulking is acceptable.

D. FIREPLACE/FIREBOX	
Possible Deficiency	Firebox paint changed by fire.
Performance Standard	None.
Responsibility	None. Heat and flames from fire will alter finish.

E. FIREPLACE/CRACKS	
Possible Deficiency	Cracked firebrick and mortar joints.
Performance Standard	None.
Responsibility	None. Heat and flames from "roaring" fires will cause cracking.

F. SKYLIGHTS	
Possible Deficiency	Leaking of skylights
Performance Standard	Skylights shall be installed in accordance with manufacture's specifications. Leaks resulting from improper installation are unacceptable. Condensation on interior surfaces is not a leak and not considered a defect.
Responsibility	Builder will repair any improperly installed skylight to meet
	Performance Standards.

10. CABINETS & COUNTERTOPS

A. COUNTERTOPS	
Possible Deficiency	Surface cracks, joint de-lamination and chips in high pressure
	laminates on vanity and kitchen cabinet countertops.
Performance Standard	High pressure laminate countertops shall not de-laminate.
Responsibility	Builder will replace de-laminated coverings to meet specified
	criteria. Builder will not be responsible for chips and cracks noted
	after settlement date.

B. CABINETS	
Possible Deficiency	Kitchen cabinet malfunctions.
Performance Standard	All doors and drawers should operate with ease. Warpage should
	not exceed 1/4 inch as measured from face frame to point of
	furthermost warpage with door or drawer front in closed position.
Responsibility	Builder will correct or replace doors or drawer fronts to meet
	Performance Standard. However, if the material is defective the
	issue will fall under the manufacturer's warranty

C. CABINET/GAPS	
Possible Deficiency	Gaps between cabinets, ceiling or walls.
Performance Standard	Acceptable tolerance is 1/4 inch in width.
Responsibility	Builder will correct to meet Performance Standard.

D. CABINET/DRAWERS	
Possible Deficiency	Cabinet drawers or door binds.
Performance Standard	Cabinet doors and drawers shall open and close with reasonable
	ease.
Responsibility	Builder will adjust or replace doors and drawers as necessary to
-	meet the Performance Standard

E. CABINET/BLEMISHES	
Possible Deficiency	Cabinets blemished
Performance Standard	Cabinets will have natural discoloration or "veins" due to the
	nature of wood, however, should be free of scratches.
Responsibility	If noted before the settlement date, cabinet doors or drawer fronts that are blemished will be corrected or replaced by Builder to meet Performance Standards. Scratches repaired with wood filler is acceptable.

10. CABINETS & COUNTERTOPS - continued

F. COUNTERTOP/BLEMISHES	
Possible Deficiency	Counter top or vanity top has scratches.
Performance Standard	All tops should be free from visible scratches during the delivery of
	your home.
Responsibility	If noted before the settlement date, Builder will repair the imperfection to meet the Performance Standards. However, if the material is defective the issue will fall under the manufacturer's warranty.

Note: All cabinetry material and workmanship is warranted by the manufacturer. Builder will only address items relating to the installation of cabinetry.

11. PLUMBING

A. WATER SUPPLY SYSTEM/FREEZES	
Possible Deficiency	Plumbing pipes freeze and burst.
Performance Standard	Drain, waste and vent, and water pipes shall be adequately
	protected, as required by applicable code during normally
	anticipated cold weather, and as defined in accordance with
	ASHRAE design temperatures, to prevent freezing.
Responsibility	Builder will correct situations not meeting the code. It is the Home
	Owner's responsibility to drain or otherwise protect exterior lines
	and faucets.

B. PLUMBING SYSTEM/LEAKS	
Possible Deficiency	Faucet or valve leak.
Performance Standard	No valve or faucet shall leak due to defects in workmanship and materials.
Responsibility	Builder will repair or replace the leaking faucet or valve during the first year of the Limited Warranty.

C. PLUMBING SYSTEM/DEFECTIVE	
Possible Deficiency	Defective plumbing fixtures, appliances or trim fittings.
Performance Standard	Fixtures, appliances or fittings shall comply with their
	manufacturer's standards.
Responsibility	Builder will repair or replace any defective fixture or fitting to meet manufacturer's standards within the first year of the Limited
	Warranty.

D. NOISY PIPES	
Possible Deficiency	Noisy water pipes.
Performance Standard	There will be some noise emitting from the water pipe system, due
	to the flow of water. However, "water hammer" shall be eliminated.
Responsibility	Builder cannot control noises due to water flow and expansion.
	Builder will take action to correct "water hammer" during the first
	year of the Limited Warranty.

E. MATERIAL BLEMISHES	
Possible Deficiency	Cracking or chipping of porcelain or fiberglass surfaces.
Performance Standard	Chips and cracks on surfaces of bathtubs and kitchen sinks can
	occur when surface is hit with sharp or heavy objects.
Responsibility	Builder will not be responsible for repairs unless damage has been
	reported to Builder on or before the settlement date.

12. HEATING AND COOLING

A. HEATING	
Possible Deficiency	Inadequate heating.
Performance Standard	Heating system shall be capable of producing an inside temperature of 70 degrees Fahrenheit, as measured in the center of each room at a height of 5 feet above the floor, under normal local outdoor winter design conditions as specified in ASHRAE handbook. Federal, state or local energy codes shall supersede this standard where such codes have been locally adopted.
Responsibility	Builder will correct heating system during the first year of the Limited Warranty to provide the required temperatures. However, the Home Owner shall be responsible for balancing dampers, registers and other minor adjustments.

B. HEAT PUMP	
Possible Deficiency	Heat pump runs continuously.
Performance Standard	On extreme outside temperatures the heating unit will work more
	frequently. If the unit still does not supply sufficient heat, the outside temperature setting on the unit may need to be adjusted.
Responsibility	None. This is Home Owner maintenance item. Please consult the manufacturer's instruction.

C. COOLING	
Possible Deficiency	Inadequate cooling.
Performance Standard	Where air conditioning is provided, the cooling system shall be capable of maintaining a temperature of 78 degrees Fahrenheit, as measured in the center of each room at a height of 5 feet above the floor, under normal local outdoor summer design conditions as specified in ASHRAE handbook. In the case of outside temperatures exceeding 95 degrees Fahrenheit, a differential of 15 degrees Fahrenheit from the outside temperature will be maintained. Federal, state, or local energy codes shall supersede this standard where such codes have been locally adopted.
Responsibility	Builder will correct cooling system to meet temperature conditions,
	in accordance with specifications during the first year of the
	Limited Warranty.

D. CONDENSATION LINES	
Possible Deficiency	Condensation lines clog up.
Performance Standard	None.
Responsibility	Condensation lines will clog eventually under normal use. This is a Home Owner maintenance item. Builder shall provide unobstructed condensation lines on the settlement date.

E. EVAPORATIVE COOLING	
Possible Deficiency	Improper mechanical operation.
Performance Standard	Equipment shall function properly at temperature standard set.
Responsibility	Builder will correct and adjust so that blower and water system
	operate as designed within the first year of the Limited Warranty.

13. VENTILATION

A. VENTALATION/DUCT WORK	
Possible Deficiency	Noisy ductwork.
Performance Standard	When metal is heated it expands and when cooled it contracts.
	The result is "ticking" or "crackling" which is generally to be
	expected.
Responsibility	None.

B. VENTALATION/OIL CANNING	
Possible Deficiency	Oil canning.
Performance Standard	he stiffening of the ductwork and the gauge of the metal used shall be such that ducts do not "oil can." The booming noise caused by
	"oil canning" is not acceptable.
Responsibility	Builder will make adjustments to meet the Performance Standard.

14. ELECTRICAL

A. ELECTRICAL CONDUCTOR/CIRCUIT BREAKERS	
Possible Deficiency	Fuses blow or circuit breakers (excluding ground fault interrupters)
	"kick out."
Performance Standard	Fuses and circuit breakers shall not activate under normal usage.
Responsibility	Builder will check wiring circuits for conformity with local, state, or
	approved correct circuitry not conforming to code specifications.

B. OUTLETS	
Possible Deficiency	Drafts from electrical outlets.
Performance Standard	Electrical junction boxes on exterior walls may produce air flow whereby the cold air can be drawn through the outlet into a room. The problem is normal in new home construction.
Responsibility	None.

C. OUTLETS/SWITCHES/FIXTURES	
Possible Deficiency	Malfunction of electrical outlets, switches or fixtures.
Performance Standard	All switches, fixtures and outlets shall operate as intended.
Responsibility	Builder will repair or replace defective switches, fixtures and
	outlets during the first year of the Limited Warranty.

D. SERVICE & DISTRIBUTION	
Possible Deficiency	Ground fault interrupter trips frequently.
Performance Standard	Ground fault interrupters are sensitive safety devices installed to
	provide protection against electrical shock. These devices are
	intended to be tripped very easily.
Responsibility	Builder shall install ground fault interrupter in accordance with
	approved electrical code. Tripping is not covered, unless due to a
	construction defect.

IV. SYSTEMS: Coverage 1st & 2nd Years

15. PLUMBING SYSTEM

A. WATER SUPPLY	
Possible Deficiency	Water supply system fails to deliver water.
Performance Standard	All on-site service connections to municipal water main shall be
	Builder's responsibility. Private systems shall be designed and
	installed in accordance with all approved building, plumbing and
	health codes.
Responsibility	Builder will repair if failure is the result of defective workmanship or
_	materials. Builder has no responsibility for conditions beyond
	Builder's control.

B. PLUMBING/PIPE LEAKS	
Possible Deficiency	Leakage from piping.
Performance Standard	No leaks shall exist in soil, waste, vent or water pipe.
	Condensation on piping does not constitute leakage, and is not
	covered.
Responsibility	Builder will make repairs to eliminate leakage.

C. SEWERS/FIXTURES/DRAINS	
Possible Deficiency	Stopped up sewers, fixtures and drains.
Performance Standard	Sewers, fixtures and drains shall operate properly.
Responsibility	Builder will not be responsible for sewers, fixtures and drains that are clogged due to Home Owners actions. Where defective construction is shown to be the case, Builder will correct the problem; where Home Owner negligence is shown to be the cause, the Home Owner shall assume all repair costs.

IV. SYSTEMS: Coverage 1st & 2nd Years - continued

16. VENTALATION SYSTEM

A. DUCTWORK	
Possible Deficiency	Ductwork separates or becomes unattached.
Performance Standard	Ductwork shall remain intact and securely fastened.
Responsibility	Builder will re-attach and re-secure all separated or unattached
	ductwork.

B. HVAC/CONDENSATION	
Possible Deficiency	Condensation on HVAC ducts in basements or crawl spaces.
Performance Standard	Ductwork carries cool air in summers and condensation will occur
	in humid areas.
Responsibility	None

C. HEATING/BASEMENT (Finished by Builder)	
Possible Deficiency	Finished basement areas are not heated properly.
Performance Standard	Basements require more heat than other parts of the home in winter. In single zone HVAC systems, since a thermostat located on the first floor normally directs the heating system, it is entirely possible that the basement may need additional heat sources.
Responsibility	None.

17. ELECTRICAL SYSTEM

A. WIRING	
Possible Deficiency	Failure of wiring to carry its designed load.
Performance Standard	Wiring should be capable of carrying the designed load for normal
	residential use.
Responsibility	Builder will check wiring for conformity with local, state, or approved national electrical code requirements. Builder will repair wiring not conforming to code specifications.

V. BUILDING CODES

APPENDIX "A": MODEL CODES

Building Codes

- BOCA Basic Building Code, Building Officials & Code Administrators International, Inc.
- National Building Code, American Insurance Association
- CABO One and Two Family Dwelling Code, Council of American Building Officials

Mechanical Codes

- Uniform Building Code, Volume II, Mechanical, International Conference of Building Officials
- BOCA Basic Mechanical Code Building Officials & Code Administrators International Inc.

Plumbing Codes

- Standard Plumbing Code, Southern Building Code Congress
- Uniform Plumbing Code, International Association of Plumbing & Mechanical Officials
- BOCA Basic Plumbing Code, Building Officials & Code Administrators International, Inc.

Electrical Codes

- Electrical Code for One and Two Family Dwelling, National Fire Protection Association
- National Electrical Code, National Fire Protection Association

VI. EXCLUSIONS

This warranty shall not extend to, include or be applicable to:

- 1. Landscaping (including sodding, seeding, shrubs, trees and plantings); off site improvements; or any other improvements not a part of the Home itself.
- 2. All equipment, appliances, materials and building components that are covered by separate manufacturers' warranties.
- 3. Loss or damage to real property which is not part of the Home and which is not included in the original purchase price of the Home stated on the Agreement of Sale.
- 4. Any damage to the extent it is caused or made worse by:
 - a. Negligence, improper maintenance or improper operation by anyone other than Builder, its employees, agents or subcontractors; or
 - b. Failure by the Home Owner or anyone else to comply with the warranty requirements of manufacturers of appliances, fixtures and items of equipment; or
 - c. Failure by the Home Owner to give notice to Builder of any defective item within a reasonable time; or
 - d. Changes of the grading of the lot by anyone other than Builder, its employees, agents or subcontractors; or
 - e. Changes, alterations or additions made to the Home by anyone after the Limited Warranty Commencement date stated on the Certificate; or
 - f. Dampness or condensation due to the failure of the Home Owner to maintain adequate ventilation;
- 5. Loss or damage which the Home Owner has not taken timely action to minimize;
- 6. Any defect in, caused by, or resulting from materials or work supplied by anyone other than Builder, its employees, agents or subcontractors;
- 7. Normal wear and tear or normal deterioration:
- 8. Loss or damage resulting from accidents, riot and civil commotion, fire, explosion, smoke, water escape, falling objects, aircraft, vehicles, Acts of God, lightning, windstorm, hail, flood, mud-slide, earthquake, volcanic eruption, wind-driven water and changes in the underground water table which were not reasonably foreseeable;
- 9. Loss or damage to personal property caused by or resulting from seepage of water
- 10. Loss or damage caused by or resulting from soil movement for which compensation is provided by legislation or which is covered by other insurance;
- 11. Insect damage;
- 12. Loss or damage arising while the Home is being used primarily for nonresidential purposes;
- 13. Any condition which does not result in actual physical damage to the Home, including, but not limited to, un-inhabitability or health risk due to the presence or consequence of unacceptable levels of radon gas, formaldehyde or other pollutants and contaminants; or the presence of hazardous or toxic on-site materials.